



**TOWN OF OXFORD**  
**DPW**  
DEPARTMENT OF PUBLIC WORKS

## ILICIT DISCHARGE REMOVAL REPORT

Location:

175 Sutton Avenue

Removal Date:

September 22, 2021

Description: (2) PVC pipes were found to be discharging into a catch basin. After sampling the effluent twice. E-Coli and fecal coliform were both present in the effluent of both pipes.

### Method & Date of Discovery:

The test results were received on 8/11/21 for the first round of testing which tested the combined effluent of both pipes, and 8/26/21 for the second round of testing which tested the effluent of each pipe individually. Microbac Labs of Dayville, CT performed the testing.

### Removal Action or Planned Corrective Measures:

On September 22, 2021 J.H. Lynch & Sons, Inc., as part of an ongoing project, removed the catch basin and capped both pipes. The resident was notified of actions taken.

### Estimated volume of flow removed from the MS4:

100qpd

DPW Director

9/27/2022

Date