



**TOWN OF OXFORD**  
**DPW**  
DEPARTMENT OF PUBLIC WORKS

## ILLEGITIMATE DISCHARGE REMOVAL REPORT

**Location:**

443 Main St.

June 19, 2018

**Removal Date:**

**Description:**

A 4-inch PVC pipe from the house at 443 Main Street was connected to catch basin, CB2-81, in Prince Street.

**Method & Date of Discovery:**

Video camera run through pipe on 1/27/2014 after receiving complaint from neighbor of an illicit connection. Gustafson Plumbing performed the video monitoring.

**Removal Action or Planned Corrective Measures:**

Owners of the property, Paul & Constance Holmberg, hired Helgerson Excavation to remove the connection by plugging the pipe inside and outside of the catch basin. Work was performed on June 19, 2018 and witnessed by Mark Allen, P.E. of Allen Engineering & Associates. Refer to August 2, 2018 Close Out Letter by engineer.

**Estimated volume of flow removed from the MS4:**

UNKNOWN *SMD*



DPW Director

*9/17/2019*

Date